Annexure D

BUILDING SAFETY CERTIFICATE

No.: 757 Dated: 18.09.2026

Certified that the existing building **INDIAN PUBLIC JUNIOR HIGH SCHOOL** (name of the building or premises) at **HARDIYA CHOWK, BANSI ROAD, BASTI (U.P.)** (Address) is having block(s)/Floor(s) as per details below:

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the blocks	G+2					

The building is owned/occupied by **INDIAN PUBLIC JUNIOR HIGH SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. Basti (Name of Department/ Govt.) on 14.09.2026 (Date of inspection) in the presence of **KAILASH NATH DUBEY S/o LATE RAM SHANKAR DUBEY R/o MAUJA- BASIA, TAPPA- HAWELI, PARGANA -BASTI PURAB, TAHSIL AND DISTT.- BASTI (U.P.)** (Name and addresses of the Manager) and that the building/premises is fit for occupancy for running school with effect from 18.09.2026 for a period of 5 **years** in accordance with rule and subject to compliance of the specific conditions as appended.

1.
2.
3.
4. /

Issued on 18.09.2026 at Basti by P.W.D. Basti

18/9

Signature with Seal: अधिशासी अभियन्ता
Name: प्रान्तीय खण्ड लो०नि०वि०, बस्ती
Designation: _____
Name & Address of Department/ Office: _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.